EasyMatch® QC Lesson 11

Using a Data Series

In the case of an ideal physical standard does not exist for your product, and so you cannot read this standard with your instrument or compare samples from your process with this standard. However, you do have a general product specification available such as the following:

X (C/2) must be between 75 and 85

Y (C/2) must be greater than 80

Z(C/2) must be less than 70.

We can use a data series to input these product specifications and then compare samples to it as if it were a standard.

- 1. **Open a new job** and configure the Color Data Table to display XYZ for C/2 and to show tolerances. You may configure the other parameters however you like.
- 2. Open the **Measurements** menu and choose **Read Series**. Name the series "Lesson 11." Note that the X, Y, and Z values for the data series are all zero.

*EasyMatchQC -	[Untitled Job6] [DataBase	: EZQC]				×
🔶 File Edit View Mea	surements Options Sensor	Window H	elp			- 8	×
	8 🛃 🛃 😒	3	0				
Eesson 11	D	X	Y	Z			
Complee	Lesson 11	0.00	0.00	0.00			
Samples	Max Tolerances	0.00	0.00	0.00			
	Min Tolerances	0.00	0.00	0.00			
	H ↓ ► ► C/2/ Color Data Table - 1	00 Wavelength (n	600))		D ⁴		
🔶 Untitled Job6	Debora di Liodirenergi ret il	anonnidance)		120 001		,000,10	_
		-					_
Ready	Curr	ent Sensor :C	olorFlex Diffus	e "CD03; Currer	nt Stdz.Mode :	Mode - RSIN	. /

- a. Right-click Lesson 11 in the Job Tree and choose **Properties**.
- b. Click Tolerances.
- c. On the **Scales** tab, choose XYZ for the scale and C/2 for the illuminant/observer and then enter the tolerances that correspond with your product specifications.

X Min = 75 X Max = 85 Y Min = 80 Y Max = No maximum value Z Min = No minimum value Z Max = 70.

icales Haze and Opacity Selected Scale : XYZ				Tolerances :		
Illuminant/Observer :	×	Min	75	Мах	85	-
C/2 <u>▼</u>	Y	Min	80	Мах		-
 Enter tolerances as absolute values 	Z	Min		Мах	70	
C Enter points for chromaticity plot						

d. Click **OK** twice to exit the Tolerances screen and the Series Properties screen. The minimum and maximum values entered now show in the tolerance rows of the Color Data Table.



3. **Read a sample** and link it to the Lesson 11 series. It will be assessed versus the minimum and maximum tolerances and pass (green)/fail (red) reported.

EasyMatchQC -	[Untitled Job6] [DataBase	: EZQC]		
🔶 File Edit View Mea	surements Options Sensor	Window H	elp		- 8 ×
	🔒 🛃 🛃 😪	<mark>(3</mark> 🗐 (3		
Lesson 11 - Samples Sample 1 Sample 1	ID Lesson 11 Max Tolerances Min Tolerances Sample 1 H P P C/2 Color Data Table - 1 Sample 1 MMAK: 10 + P1 C/2 Color Data Table - 1 Sample 1 MMAK: 10 + P1 Lesson 11 P0 MMAK: 10 + P1 C/2 Color Data Table - 1 Sample 1 Sample 1 Sample 1 Sample 2 Sample 2	X 0.00 85.00 75.00 81.62	Y 0.00 80.00 83.62	Z 0.00 70.00 99.26	
🔶 Untitled Job6					
Ready	Curr	ent Sensor :C	olorFlex Diffus	e "CD03: Curre	nt Stdz.Mode : Mode - RSIN · 🏑