How much time does it take to measure color and haze?

A typical color measurement takes at most 2 seconds, with a measurement of both color and haze takes 5 seconds. The haze measurement using light trap and white tile is done automatically in Vista without intervention required by the operator.