The requirement of an operator to perform a green tile check as part of sensor standardization can be selected from the SYSTEM SETTINGS/DIAGNOSTIC/ STDZ CHECK menu. The default value is NO (Green tile check is not performed), and can be changed to YES if required (Green Tile Check is included in Standardization).

STDZ CHECK = NO - Only the Black and White Tile are used during Standardization

STDZ CHECK = YES - Black, White, and Green Tile are used during Standardization.